

REG NO N758HV CHANDLER AVIATION INC DATE 02/18/16
 MODEL 172XP CHANDLER MUNICIPAL WO# 53003
 S/N R1723117 CHANDLER, AZ HOBBS 00.0
 ENG MOD IO360KB (480) 732-9118 TACH 1002.4
 ENG S/N 356198 TOTAL 3008.5

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE *[Signature]* AUTH. NO. 2307335 A&P

Cleaned & lubed all flight controls and nose gear. Clean flap tracks and re-lube rollers and tracks. Install new landing and taxi light switches. Replace power wire to Hobbs meter switch. Found power going to meter but meter inop. Install new Hobbs hour meter at meter reading 00.0. Previous meter reading is 1341.9. Opened all panels, removed seats and lubed pulleys, bellcranks, and flight controls. Clean and grease all wheel bearings. Install new nose wheel bearings. Install new nose wheel tire and tube. Install new instrument air vacuum filter. Install new access door springs to MLG wheel fairings. Re-torque upper aft cowl mounts. Install customer provided 406Mhz ELT using new mounting tray and installation kit. Ops tested and inspected ELT in accordance with FAR 91.207(d). Remove shimmy dampener and reseal. Remove nose strut and replace strut seals and scraper. Service with 5606 and N2. Install new fuel caps. C/W AD 2011-10-09 seat rails and rollers. Measure and inspect, determined to be satisfactory. Next due Feb 28, 2017. See Customer provided adlog system. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

END

REG NO N758HV CHANDLER AVIATION INC DATE 01/12/17
 MODEL 172XP CHANDLER MUNICIPAL WO# 54014
 S/N R1723117 CHANDLER, AZ HOBBS 24.1
 ENG MOD IO360KB (480) 732-9118 TACH XX
 ENG S/N 356198 TOTAL XX

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE *[Signature]* AUTH. NO. 2307335 A&P

Clean contacts on fuel gauge for oil temp and CHT. Clean leads at fuel sending units and fuel gauge. Replaced power lead on Insight engine monitor. Remove and replaced light bulb. Ops checks satisfactory.

END

REG NO N758HV CHANDLER AVIATION INC DATE 02/10/17
 MODEL 172XP CHANDLER MUNICIPAL WO# 54016
 S/N R1723117 CHANDLER, AZ HOBBS 25.2
 ENG MOD IO360KB (480) 732-9118 TACH 1024.3
 ENG S/N 356198 TOTAL 3030.4

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE *[Signature]* AUTH. NO. 2307335 IA

Cleaned & lubed all flight controls and nose gear. Lube flap rollers and tracks. Inspected ELT in accordance with FAR 91.207(d) next battery replacement due Nov. 2020. Remove and replace Tail nav/light with new bulb. Adjust (2) cowl attach cam locks and lube. Sand minor corrosion aft of battery box vent drain with scotch bright pad to exterior skin. Prime and touch up white paint. Replace broken fuse for instrument panel clock with new. AD 2011-10-09 Seat measure. Remove, measure and visually inspect. Next due Feb 28, 2018. AD 2001-23-03 R1 fuel line inspect per action (1). AD 93-05-06 Gerdes switch not due until 3898.2 total time A/F. Update AD listing to update 2017-02. See AD listing for all updated AD's. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

END

REG NO N758HV **CHANDLER AVIATION INC** DATE 03/09/18
MODEL 172XP CHANDLER MUNICIPAL WO# 55049
S/N R1723117 CHANDLER, AZ HOBBS 25.2
ENG MOD I0360KB (480) 732-9118 TACH 1046.9
ENG S/N 356198 TOTAL 3053.0

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE [Signature] AUTH. NO. 2307335 IA

Cleaned & lubed all flight controls and nose gear. Lube flap rollers and tracks. Inspected ELT in accordance with FAR 91.207(d) next battery replacement due Nov. 2020. Remove and replace o-rings on shimmy dampener and service with 5606. Remove, file and install cat track on baffle near engine case to prevent rubbing. Clean and lube flap tracks. C/W AD 2011-10-09 Seat measure. Remove, measure and visually inspect. Next due annually. AD 2001-23-03 R1, Chafing. Found satisfactory, next due 1146.9 tach time. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

END

REG NO N758HV **CHANDLER AVIATION INC** DATE 03/30/18
MODEL 172XP CHANDLER MUNICIPAL WO# 55150
S/N R1723117 CHANDLER, AZ HOBBS 25.2
ENG MOD I0360KB (480) 732-9118 TACH 1046.9
ENG S/N 356198 TOTAL 3053.0

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE [Signature] AUTH. NO. 2307335 A&P

Remove and replace battery with new G-242 battery and service. Serial Number G02993007.

END

REG NO N758HV **CHANDLER AVIATION INC** DATE 05/24/18
MODEL 172XP CHANDLER MUNICIPAL WO# 55202
S/N R1723117 CHANDLER, AZ HOBBS 54.4
ENG MOD I0360KB (480) 732-9118 TACH 1048.4
ENG S/N 356198 TOTAL XXX

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE [Signature] AUTH. NO. 206463594 A&P

Adjust micro switches on flap handle. Ops check satisfactory.

END

REG NO N758HV **CHANDLER AVIATION INC** DATE 05/30/18
MODEL 172XP CHANDLER MUNICIPAL WO# 55215
S/N R1723117 CHANDLER, AZ HOBBS 55.2
ENG MOD I0360KB (480) 732-9118 TACH 1049.9
ENG S/N 356198 TOTAL XXX

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ON THE DATE STATED ABOVE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY.

SIGNATURE [Signature] AUTH. NO. 206463594 A&P

Remove and replace vacuum pump with overhauled unit. See 8130-3 dated Dec 12, 2017 from Airpower Accessories with W/O 008979. P/N 215CC S/N 1212179. Op check satisfactory.

END